

# LAKEHURST

---

LOCATION: Seattle, Washington  
BUILDING TYPE: Condo - 34 units  
TOTAL REPAIR COST: \$1,875,000.00  
REPAIRS COMPLETED: 2008

## CONSTRUCTION REPAIRS INCLUDED:

- Replacement of all existing siding with new lap siding system.
- New composition shingle roofing.
- Aluminum picket-style guardrail installation.
- New metal gutters & downspouts.
- Restoration of interior finishes.



S9a